



# Label and Track a Peak

Enables a label on a peak value in 2D displays that tracks with the peak value.


1. Right click on the 2D display and select Value Table



2. Select Max as label (also can use legend or popup)



3. Now the peak value will be displayed



4. If you have more than one channel displayed it still works – you can manually move around the labels so you can see them all

